

28/08/2016

Hi Conor,

Thank you for giving Bord Gáis Energy Ltd the opportunity to reply to this code modification. The recent imbalances have impacted negatively on the gas system and has affected all shippers in that more Bal sells are occurring on the system at an extra cost. Bord Gáis welcome any amendment to address this situation. Increasing the second tier imbalance from 0.05 to 0.25 should encourage all shippers to manage their imbalance position more prudently with a view to staying balanced. Therefore Bord Gais Energy are in favour of moving second tier imbalance price to 0.25.

Best regards
Kevin

Kevin Murray
Operations Manager

Bord Gáis Energy Ltd.
1st Floor, Building 6900, Cork Airport Business Park, Cork, Ireland
Tel: +353 21 493 7502 Fax: +353 21 4937565
Mob: +353 87 624 8241 www.bordgaisenergy.ie