



Leak Summary Sheet

UAV-Based Type 2 LDAR Surveys, Q2 2025

Issued by: SurveyLabs Ireland (info@surveylabs.ie)

Reference documents: Method Statement, Compliance Statement, Site Reports 1–14

August 3, 2025

Copyright

© [2025] [SurveyLabs Ltd]

All rights reserved. Permission is hereby granted to **Gas Networks Ireland** to use, modify, distribute, and reproduce the contents in any manner they see fit, without any restrictions or need for further authorization.

Contact

Webpage: SurveyLabs.ie

Contact: Gerard Dooly, gerard.dooly@surveylabs.ie, +353863736889

Changelog

v1.0	Aug 2025	Initial release of the report.
------	----------	--------------------------------

Table of Contents

1 Survey Area Status 4

1 Survey Area Status

Area	Location	Survey Status	Notes
1	Brian Boru Bridge	Completed	No leak detected
2	Clontarf Bridge (identical to Area 1)	Not Applicable	Pipeline previously removed; no survey required
3	Shannon Estuary Tx Crossing (1.875 km)	Completed	No leak detected
4	Little Island to Mahon Tx Crossing (750 m)	Completed	No leak detected
5	Mahon to Rochestown Tx Crossing (406 m)	Completed	No leak detected
6	37 Lucan Sewage Treatment Works, Dublin	Completed	No leak detected
7	Mulhuddart Bridge, Dublin	Completed	No leak detected
8	42 Cabra Rd., Dublin	Completed	No leak detected
9	25 Bull Ring, Drogheda	Completed	No leak detected
10	Alexandra Bridge, Clare	Completed	No leak detected
11	3774810-RVX-MP-273, Arklow Bridge	Completed	No leak detected
12	Parteen Bridge, Clare	Completed	No leak detected
13	Greens Bridge, Kilkenny	Completed	No leak detected
14	R463, Ardnacrusha, Clare	Completed	No leak detected